



Primary Sound Patchbay Layout January 2022

All SSL patch points are standard on all 4000's